




Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
MANCHESTER ROAD	o/s 681	Decay	Poor specimen, stem broken; senescent.	Sorbus aucuparia sp	Plant in verge centrally o/s 681 (same position)	
MANCHESTER ROAD	o/s 565	Structural	Extensive stem wounding, structural integrity in doubt	Sorbus aucuparia	Plant in verge o/s 565, (same as felled tree)	